



Found corner Established by the line block 48x6x2 19x12x7 & 3/4 line block

Found corner Established by the line block 18x8x5 & 5 hard block 10x10 bearing true Br. 10° 40' to 10 1/4 links

Found corner Established by the line block 15x6x4

2nd hard block 18x8x5 & 5 hard block 10x10 bearing true Br. 10° 40' to 10 1/4 links

Found point of block the water had washed the block away from corner drove from block in the place of the old one & surrounded it with 4 line block

I hereby Certify that the above is a correct record and plat of a survey made by me on Section 32 Bradford, May 1<sup>st</sup> 1877

Edward Ruger  
County Surveyor  
of Rock County