

Of a Survey on Section 19 T 4 R 10 E. of the 4 P. M. in Union Township

Rock County, Wisconsin, made Nov the 9th 1860

I hereby certify that the following is a correct record of said survey as made by me.

(Signed) Edward Ruger
R.H.B. County Surveyor.

	Set hard head 16x8x3 + surrounded it by 8 hard heads	Set limestone 12x5x3 + set lime stone on the N + S sides	Set hard head 14x12x9 + surrounded it by 4 hard heads	Set lime 17x8x7	
	23.14 1/2	19.95 1/2	20.10	20.10	had been stone put in for corner
		Set hard head 17x5x4 + set hard head on N + S sides	Set limestone 18x8x2 1/2 + surrounded it by 4 lime stones	Set hard head 12x10x5	
Set hard head x 8x7 + surrounded it by 4 hard heads	23.88	20.05	20.05	20.05	Set lime stone 12x6x3 + surrounded it by 3 lime stones
	20.88*				
	24.43	19.99	20.06	20.06	Set lime stone 18x9x6 + surrounded it with small lime stones
Set lime stone 20x10x7 + set sand stone on south + lime stone on north sides		Set limestone 10x6x2	Set hard head 14x8x7	Set limestone 14x6x2	

* COPIED FROM PG 8 BOOK BY RUGER FIELD NOTES
1/21/76 DAB

Copied from page 158 Vol. 1. Original County Surveyors Record